

Stapler



Pneumatic stapler. Used for joining of various mesh and panel solutions at slopes and along cuts.

Stock programme:

Model AC50. Supplied in a case.

Technical information:

Normal operational compressed air pressure: 6-8 Bar.

Weight 6.6 kg.

Magazine for 100-120 staples (2 strips of 50 pcs.)

Accessories:

Galfan C-Rings (staples) in boxes of 1600 pcs. or pallets of 130 boxes.

Each strip contains 50 pcs. staples.